

PACKING LIST

- 1 - Problast 3 Cabinet
- 1 - Instructions
- 1 - DC Power Supply

INSTALLATION & OPERATION

1. Remove the unit and all packaging material from the box.
2. Plug the DC Power Supply into an electrical outlet, then into the right side of the light assembly.

REPLACEMENT PARTS

Fig. #	Description	Reorder Part Number
1	Floor Screen	2240
2	LED Light Assembly	97969
3	Window Bracket Assembly (with glass)	2282
4	Pin-Hinge Assembly	2290
5	Window	2241
6	Protector Shield	97951
7	Cuff Holder	2260
8	Cuff (Black Cloth)	2033XL
9	Window Gasket Kit	2030B